


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Unsurveyed- Subdivided Section



No record of subsequent remonumentation found in County Records.

Description of corner evidence found:

NONE.

Description of monument and accessories established to perpetuate the original location of this corner

Set 2 1/2" x 30" iron pipe <sup>6"</sup> in ground. Raised rock mound to the top of brass cap. Brass cap is marked as shown from which I scribed bearing trees.


A Tamarack 20in. diam. brs. N 75° W 72.00ft. marked CS 1/16 S6 BT  
A Fir 8in. diam. brs. S 60° W 33.35ft. marked CS 1/16 S6 BT

Nailed a brass washer marked PLS 933 to the BT blaze of trees. Set a steel post 4ft. North of corner. Corner is 175ft. South of North fork road. Used T-2 and steel tape, measuring a horizontal distance to the center of the bearing trees.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*David H. Krumbain*

OREGON  
JULY 17, 1970  
DAVID H. KRUMBAIN  
933



Office of County Surveyor County of Grant  
State of Oregon, I hereby certify that the within instrument was filed in this office  
for record on the 20 day of Sept, 1978.  
Robert D. Baggett by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)