

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Unsurveyed - subdivided section.

DIAGRAM
T 7S R 33E
SE 1/16 S 6

No record of subsequent remonumentation found in County Records.

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner

Set $2\frac{1}{2}$ " x 30" iron pipe in ground. Placed rock collar around brass cap. Cap marked as shown from which I scribed bearing trees:

- A pine 13 in. diam. brs. N $13^{\circ}09'$ E 54.76 ft. marked SE 1/16 S6 BT
- A pine 22 in. diam. brs. S $18^{\circ}04'$ W 33.49 ft. marked SE 1/16 S6 BT

Nailed brass washer marked PLS 933 to BT blaze of trees. Set steel post 3 ft. North of corner. Corner is East 800 ft. from a road. Used T-2 and steel tapes measuring a horizontal distance to the center of bearing trees.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David H. Krumbein

OREGON
JULY 17, 1970
DAVID H. KRUMBEIN
933

T 7S R 33E
SE 1/16 S 6
1978
PLS 933

Office of County Surveyor County of Grant
State of Oregon I hereby certify that the within instrument was filed in this office
for record on the 20 day of Sept. 1978
Robert D. Bazett by
(COUNTY OFFICIAL) (DEPUTY)