


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None

This corner was established as part of a subdivisional section breakdown survey, marking property boundaries between U. S. Forest Service and private parcels.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set: A 2½ in. by 30 in. galv. iron pipe, with a 2½ in. brass cap, 27 in. in the ground with a mound of earth to the cap, from which:

A reference monument bears S73°E - 15.00 ft., marked:
S21 T7S R35½E 15.00 ft. N1/16 RM 1106

A reference monument bears N38½°E - 15.00 ft., marked:
S21 T7S R35½E 15.00 ft. N1/16 RM 1106

Set a steel fence post (guard post), with a 54-9 sign attached, near each reference monument.

Note: A reference monument is a 1½ in. aluminum cap on a 5/8 in. by 30 in. iron pin.

Set a steel fence post, with 54-9 sign attached, North of monument.


Cap marked:

This corner was monumented on October 28, 1983.

Witnessed by: Robert D. English
James Bowler

REGISTERED PROFESSIONAL LAND SURVEYOR

<i>William R. Wells</i> OREGON JULY 22, 1977 WILLIAM R. WELLS 1106
--



Office of... County Surveyor..... County of... Grant
 State of... Oregon....., I hereby certify that the within instrument was filed in this office
 for record on the... 15 day of... Oct....., 1983
Robert D. English by.....
 (COUNTY OFFICIAL) (DEPUTY)