CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1884 by William Barr, Under General Land Office Contract No. 492. Surveyor Generals Notes State:
Set basalt stone 20x16x8" 15" in the ground for ¼ section corner marked ¼ on N face.
From which:
A Tamarack 10" dia. bears N70°W, 27 lks dist marked ¼ S BT.
A Pine 10" " " S30°E, 62 " " " " " "

DIAGRAM

T7S R35½E
S27
¼ —·— S34
1983
PLS848

Description of corner evidence found:

Found 20"x13"x8" stone with 4 visible chissled on North face(4 is smaller than normal) set firmly in the ground.
No evidence of original bearing trees found, accepted stone as position of ¼ corner.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 30"x2"½ aluminum pipe with a 2½" aluminum cap stamped as shown in diagram.
Set 24" in the ground, set original stone North alongside pipe.
From which:
A Lodge-pole Pine 6" dia. bears N12°W, 36.1 ft. scribed ¼ S27 BT.
A " " " 6" " " S15°E, 13.0 ft. " ¼ S34 "
Set steel post with warning sign North 3 ft.
Nailed brass washers stamped PLS848, bearing tree and warning signs to each tree.
Painted 6" red band around each tree.

REGISTERED PROFESSIONAL LAND SURVEYOR
OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Corner monumented 8-22-83
Witnessed by Dan Martin

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 22 day of Nov, 19 83
Robert D Bagett by
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

☆GPO—798-276

V-15