


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None

This corner was established as part of a subdivisional section breakdown survey, marking the property boundaries between U. S. Forest Service and private parcels.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set: A 2½ in. by 30 in. aluminum pipe, with a 2½ in. aluminum cap, 27 in. in the ground with a mound of earth to the cap, from which:

A 5½ in. dia. Lodgepole Pine bears N9°E - 115.3 ft., scribed: C1/4 S11 BT

A 11½ in. dia. Fir bears S36°E - 76.4 ft., scribed: C1/4 S11 BT

Each new bearing tree has a brass washer stamped PLS 1106 nailed to the face of the blaze, and has 54-3 and 54-9 signs attached. Painted face of blaze and a 6 in. band around each bearing tree red.

Set a steel fence post, with 54-9 sign attached, South of the monument.

Used a steel tape and a magnetic staff compass, with 20° East declination. Measured to the center of the bearing trees.

This corner was monumented on September 27, 1983.


Witnessed by: Robert D. English  
Eric Giesler

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

Cap marked:



Office of... County Surveyor..... County of... Grant  
State of... Oregon....., I hereby certify that the within instrument was filed in this office  
for record on the... 15 day of... OCT....., 19... 83  
*Robert D. English* by .....  
(COUNTY OFFICIAL) (DEPUTY)