


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None

This corner was established as part of a subdivisional section breakdown survey, marking property boundaries between U. S. Forest Service and private parcels.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set: A 2½ in. by 30 in. aluminum pipe, with a 2½ in. aluminum cap, 26 in. in the ground with a mound of earth to the cap, from which:

- A 7 in. dia. Lodgepole Pine bears N5½°W - 10.0 ft., scribed: C1/4 S14 BT
- A 9 in. dia. Lodgepole Pine bears S49°W - 36.3 ft., scribed: C1/4 S14 BT

Each new bearing tree has a brass washer stamped PLS 1106 nailed to the face of the blaze, and has 54-3 and 54-9 signs attached. Painted the face of the blaze and a 6 in. band around each bearing tree red.

Set a steel fence post, with 54-9 sign attached, North of the monument.

Used a steel tape and a magnetic staff compass, with 20° East declination. Measured to the center of the bearing trees.


This corner was monumented on September 12, 1983.

Witnessed by: Robert D. English  
Aaron C. Hoeft

Cap marked:

REGISTERED PROFESSIONAL LAND SURVEYOR
---

<i>William R. Wells</i>
OREGON JULY 22, 1977 WILLIAM R. WELLS 1106



Office of... County Surveyor ..... County of... Grant .....  
 State of... Oregon ..... I hereby certify that the within instrument was filed in this office  
 for record on the 15 day of Oct ..... 1983  
*Robert D. English* by .....  
 (COUNTY OFFICIAL) (DEPUTY)