


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None

Corner was established as part of a subdivisional section breakdown survey, to determine property boundaries of U. S. Forest Service and private parcels.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set: A 2½ in. by 30 in. aluminum pipe, with a 2½ in aluminum cap, 20 in. in the ground with a mound of earth to the cap, from which:

- A 9 in. dia. Lodgepole Pine bears N37°E - 87.8 ft.,
scribed: SE 1/16 S14 BT
- A 7½ in. dia. Lodgepole Pine bears S48½°W - 81.6 ft.,
scribed: SE 1/16 S14 BT

Each new bearing tree has a brass washer stamped PLS 1106 nailed to the face of the blaze, and has 54-3 and 54-4 signs attached. Painted the face of the blaze and a 6 in. band around each bearing tree red.

Set steel fence posts (A) East of the monument with 54-2 and 54-9 signs attached, and (B) South of the monument with a 54-2 sign attached.

Used a steel tape and a magnetic staff compass, with 20° East declination. Measured to the center of the bearing trees.

This corner was monumented on September 8, 1983.


Witnessed by: Robert D. English
Aaron C. Hoefl
Eric Geisler

REGISTERED PROFESSIONAL LAND SURVEYOR

William R. Wells

OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

Cap marked:



Office of.....County Surveyor..... County of.....Grant.....
 State of.....Oregon....., I hereby certify that the within instrument was filed in this office
 for record on the 15 day of Oct, 1983.
Robert D. English by
 (COUNTY OFFICIAL) (DEPUTY)