


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None

Corner was established as part of a subdivisional section breakdown survey, marking the property boundaries between U. S. Forest Service and private parcels.

Description of monument and accessories established to perpetuate the original location of this corner:

Set: A 2½ in. by 30 in. aluminum pipe, with a 2½ in aluminum cap, 28 in. in the ground with a mound of earth to the cap, from which:

- A 11 in. dia. Lodgepole Pine bears N51°E - 30.1 ft., scribed: S1/16 S13 BT
- A 13½ in. dia. Lodgepole Pine bears N17°W - 37.1 ft., scribed: S1/16 S14 BT

Each new bearing tree has a brass washer stamped PLS 1106 nailed to the face of the blaze, and has 54-3 and 54-9 signs attached. Painted the face of the blaze and a 6 in. band around each bearing tree red.

Set a steel fence post, with 54-2 and 54-9 signs attached, East of the monument, and post with sign 54-2 attached West of monument.

Used a steel tape and a magnetic staff compass, with 20° East declination. Measured to the center of the bearing trees.

This corner was monumented on September 8, 1983.


Witnessed by: Robert D. English  
Aaron C. Hoeft.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

Cap marked:



Office of..... County Surveyor..... County of..... Grant  
 State of..... Oregon....., I hereby certify that the within instrument was filed in this office  
 for record on the 15 day of Oct, 1983.  
*Robert D. English* by.....  
 (COUNTY OFFICIAL) (DEPUTY)