


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None

This corner was established as part of a subdivisional section breakdown survey, marking property boundaries between U. S. Forest Service and private parcels.

Description of monument and accessories established to perpetuate the original location of this corner:

Set: A 2½ in. by 30 in. aluminum pipe, with a 2½ in. aluminum cap, 4 in. in the ground with a large mound of stone to the cap, from which:

A 7½ in. dia. Lodgepole Pine bears N76°W - 34.7 ft., scribed: E 1/16 S13 BT
 A 8 in. dia. Lodgepole Pine bears S43°E - 38.8 ft., scribed: E 1/16 S24 BT

Each new bearing tree has a brass washer stamped PLS 1106 nailed to the face of the blaze, and has 54-3 and 54-9 signs attached. Painted the face of the blaze and a 6 in. band around each bearing tree red.

Set steel fence posts (A) East of the monument with 54-2 and 54-9 signs attached, and (B) South of the monument with a 54-2 sign attached.

Used a steel tape and a magnetic staff compass, with 20° East declination. Measured to the center of the bearing trees.

This corner was monumented on September 14, 1983.


Witnessed by: Robert D. English
Aaron C. Hoeft

Cap marked:

REGISTERED PROFESSIONAL LAND SURVEYOR

William R. Wells

OREGON JULY 22, 1977 WILLIAM R. WELLS 1106



Office of...County...Surveyor..... County of...Grant.....
 State of...Oregon....., I hereby certify that the within instrument was filed in this office
 for record on the 15 day of Oct, 1983
Robert D. English by
 (COUNTY OFFICIAL) (DEPUTY)