


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None

This corner was established as part of a subdivisional section breakdown survey, marking property boundaries between U. S. Forest Service and private parcels.

Description of monument and accessories established to perpetuate the original location of this corner:

Set: A 2½ in. by 30 in. aluminum pipe, with a 2½ in. aluminum cap, 22 in. in the ground with a mound of earth to the cap, from which:

A R.M. bears N42½°W - 12.00 ft., marked: S24 12.00 ft. 1106

A R.M. bears N42°E - 12.00 ft., marked: S24 12.00 ft. 1106

Set steel fence posts (guard posts), with 54-9 signs attached, by reference monuments.

Note: A reference monument (R.M.) is a 1½ in. aluminum cap on a 5/8 in. by 30 in. iron pin.

Set steel fence posts (A) North of the monument with 54-2 and 54-9 signs attached, and (B) West of the monument with a 54-2 sign attached. Used a steel tape and a magnetic staff compass, with 20° East declination. Measured to the center of the bearing trees.

Cap marked:


This corner was monumented on September 9, 1983.

Witnessed by: Robert D. English
Aaron C. Hoeft

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106



Office of...County...Surveyor..... County of...Grant.....

State of...Oregon....., I hereby certify that the within instrument was filed in this office

for record on the 15 day of Oct, 1983

Robert D. English by _____

(COUNTY OFFICIAL)

(DEPUTY)