


**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

0-24

**History of original corner establishment:**

1983, WILLIAM R. WELLS, PLS 1108, IN GRANT COUNTY SURVEY NO. 836, ESTABLISHED THIS CORNER WHEN HE SUBDIVIDED THE SECTION. WELLS SET A 2 1/2" BY 30" ALUMINUM PIPE, WITH A 2 1/2" ALUMINUM CAP, 22" IN THE GROUND, FROM WHICH:  
REFERENCE MONUMENT, 1 1/2" ALUMINUM CAP ON 5/8" BY 30" IRON PIN, BEARS N. 42 1/2" W., 12.00 FEET.  
REFERENCE MONUMENT, 1 1/2" ALUMINUM CAP ON 5/8" BY 30" IRON PIN, BEARS N. 42" E., 12.00 FEET.



1993, DAVID A. SCHLAICH, RLS 2308, IN GRANT COUNTY SURVEY NO. 1310, FOUND THE CORNER AS DESCRIBED WITH THE EXCEPTION THAT THE 1 1/2" ALUMINUM CAP WAS MISSING FROM THE NORTHWEST 5/8" REBAR.

**Description of corner evidence found:**

FOUND REFERENCE MONUMENTS SET BY WELLS (CORNER MONUMENT IS MISSING).

A 5/8" REBAR, WITH 1 1/2" ALUMINUM CAP, PROJECTING 2" OUT OF THE GROUND, N. 42" E., 12.0 FEET, MARKED "S24 12.00 FT 1106".  
A 5/8" REBAR PROJECTING 4" OUT OF THE GROUND, N. 42 1/2" W., 12.0 FEET.

**Description of monument and accessories I established to perpetuate the original location of this corner:**

AT RECORD BEARING AND DISTANCE FROM THE REFERENCES I SET A 2 1/2" BY 30" ALUMINUM PIPE, WITH 3 1/4" ALUMINUM CAP, 29" IN THE GROUND MARKED AS SHOWN (SEE DIAGRAM).

NAD83(1991)  
LATITUDE: 44°56'51.16375" NORTH  
LONGITUDE: 118°26'27.17732" WEST

MAGNETIC DECLINATION: 18°30' EAST

WORKED PERFORMED BY: DAVID A. SCHLAICH  
WITNESSED BY: RACHELLEL (SHELLEY) FLETCHER  
DATE: JULY 18, 1995

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*David A. Schlaich*

OREGON  
JULY 16, 1987  
DAVID A. SCHLAICH  
2308

RENEWS 06/30/96

Office of SURVEYOR County of GRANT  
State of OREGON, I hereby certify that the within instrument was filed in this office  
for record on the 1st day of SEPTEMBER, 1995  
Ronald D. Baggett by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)