


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None

This corner was established as part of a subdivisional section breakdown survey.

Description of monument and accessories established to perpetuate the original location of this corner:

Set: A 2½ in. by 30 in. aluminum pipe, with a 2½ in. aluminum cap, 26 in. in the ground with a mound of stone to the cap, from which:

- A 6 in. l.p. Pine bears S89°E - 224.1 ft., scribed: C 1/4 S23 BT
- A 1½ in. reference monument bears N33°E - 12.00 ft., marked: S23 12.00 ft.

Note: A reference monument is a 1½ in. aluminum cap on a 5/8 in. by 30 in. iron pin.

1106

Set a steel fence post (guard post) with 54-9 sign attached by reference monument.

Each new bearing tree has a brass washer stamped PLS 1106 nailed to the face of the blaze, and has 54-3 and 54-9 signs attached. Painted the face of the blaze and a 6 in. band around each bearing tree red.


Set a steel fence post, with 54-9 sign attached, North of the monument.

Used a steel tape and a magnetic staff compass, with 20° East declination. Measured to the center of the bearing trees.

This corner was monumented on September 8, 1983.

Witnessed by: Robert D. English
Aaron C. Hoeft

Cap marked:



Office of.....County.....Surveyor..... County of.....Grant.....
State of.....Oregon....., I hereby certify that the within instrument was filed in this office
for record on the...15... day of...Oct... 1983
Edward D. English by
(COUNTY OFFICIAL)

(DEPUTY)
REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells
OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

☆ GPO—798-276