

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Amended Monument

History of original corner establishment:

Corner established by Herman D. Gradon, under contract No. 499 dated March, 1884.

The original notes state that at the corner:

A 6 in. dia. Pine marked T7S S25 on Southwest face (blaze), R35E S24 on Northwest face (blaze), with 4 notches on the North and 2 notches on the South, from which:

A 7 in. dia. Pine bears S55°W - 7 lks (4.6 ft.) marked: T7S R35E S25 BT

A 6 in. dia. Pine bears N30°W - 9 lks (5.9 ft.) marked: T7S R35E S24 BT

For history of 1974 BLM remonumentation, see attached sheet.


Description of corner evidence found:

A 3 1/4 in. dia. brass cap on iron pipe, marked as per diagram, from which:

A 6 in. dia. Tamarack bears S89 1/2°W - 67 lks (44.2 ft.) with visible scribing partially healed.

A 7 1/2 in. dia. Tamarack bears N28°W - 20.5 lks (13.5 ft.) with healed blaze.

Also standing is a 3' high section of the original l.p. pine corner tree with notches and scribing visible.



Description of monument and accessories established to perpetuate the original location of this corner:

Attached 54-3 and 54-4 signs, and painted the face of the blaze and a 6 in. band around each bearing tree red.

Set a steel fence post, with a 54-4 sign attached, North of the monument.

Used a steel tape and a magnetic staff compass, with 20° East declination. Measured to the center of the bearing trees.

This corner was maintained on September 15, 1983.

Witnessed by: Robert D. English
Aaron C. Hoeft

"AM" for Amended Monument was stamped on the BLM cap as shown in the diagram.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

Office of..... County Surveyor..... County of..... Grant.....
State of..... Oregon..... I hereby certify that the within instrument was filed in this office
for record on the 15 day of Oct..... 1983
Robert D. English by.....
(COUNTY OFFICIAL) (DEPUTY)