CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:
Corner not previously established.

DIAGRAM

T7S R35½E
NW-SW
1/64 S34
1983
PLS848

Description of corner evidence found:

N/A

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 30"x2½ aluminum pipe with a 2½" aluminum cap stamped as shown in diagram.
Set 12" in tailings and raised a large mound of stone to top of pipe.
From which:

A Spruce 8" dia. bears S82½°W, 29.5 ft. scribed NW-SW 1/64 S34 BT.
A Lodge-pole Pine 7" dia. bears N63°E, 77.4 ft. scribed NW-SW 1/64 S34 BT.
Set steel post with warning and boundry signs West 2 ft.
Nailed brass washers stamped PLS848, bearing trees and warning signs to each tree.
Painted 6" red band around each tree.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Douglas M. Ferguson

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

Corner monumented 8-29-83

Witnessed by Dan Martin

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 22 day of Nov, 19 83
Robert D Bagett by .....
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

GPO—798-276

X½ - 13½