


## CORNER RESTORATION

N.  $\frac{1}{4}$  cor. sec. 24  
 CORNER \_\_\_\_\_ TWP 8 S., RANGE 30 E., W.M.  
 ORIGINAL SURVEY BY: F.W. Campbell  
 CONTRACT NUMBER: 380  
 CONTRACT DATE: March 19, 1881



**ORIGINAL DESCRIPTION:**

Set a basalt stone 15x10x8 and raised mound of stone for  $\frac{1}{4}$  cor.

**RESTORATION BY, STAMP AND DATE:**

Bagett & Griffith Surveying  
 John Day, Oregon  
 April 11, 1970



**EVIDENCE FOUND:**

Basalt stone 15"x10"x8" mkd.  $\frac{1}{4}$  set in a mound of stone.

**DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:**

Show how trees are scribed and basis of bearings, including compass var.

Set a 1"x30" iron pipe 16 ins. in the ground, with brass cap mkd. as shown.  
MONUMENT MARKED

from which;  
 A juniper 12 ins. diam., bears N.85°E., 71.3 ft., mkd.  
 $\frac{1}{4}$  S13 BT.

A juniper, 14 ins. diam., bears S14°W., 92.1 ft., mkd.  
 $\frac{1}{4}$  S24 BT.

Raised a mound of stone, 3 ft. base, at cor. pipe.

Complete and File with Office of the Grant  
 County Surveyor, Grant County, Oregon,  
 Courthouse, Canyon City, Oregon 97820

Chain & compass.  
 Var. 20° East.

