

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


History of original corner establishment:

Corner established by Herman D. Gradon under GLO contract No. 499 dated March 11, 1884.

Surveyor's General records state:

Set a post 4 ft. long 4 ins. square 24 ins. in the ground for cor. to secs. 24 and 25 marked:  
T 8 S S 25 on the SW, R 35 E S 24 on the NW faces with 4 notches on the N and 2 notches on the S edges from which:

- A pine 10 ins. diam. bears S 52° W., 19 lks dist marked T 8 S R 35 E S 25 BT
- A pine 12 ins. diam. bears N 59° W., 56 lks dist marked T 8 S R 35 E S 24 BT




Description of corner evidence found:

A pine 22 ins. diam. with full scribes on open blaze for sec. 25 BT.  
The corner location as determined by the bearing tree is in an old skid trail and no trace of the original post was found.

Description of monument and accessories established to perpetuate the original location of this corner:

Set a 2½ in. brass cap on a 2 in. iron pipe 31 ins. long 27 ins. in the ground with a surrounding rock mound.

Brass cap marked thus:



New bearing tree:

A fir 6 ins. diam. bears N 80° W., 30.0 ft. dist. marked 1/4 S 24 BT.

I hereby certify the above corner monument was properly re-established by me on Sept. 6, 1979 and witnessed by John Mitchell and Don Pedracini.

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*William L. Hanley*

OREGON  
JULY 14, 1978  
WILLIAM L. HANLEY  
1639

Office of Surveyor County of Grant  
State of Oregon, I hereby certify that the within instrument was filed in this office  
for record on the 24 day of Sept, 1979  
Robert D. Begett by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)