


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

S-18

History of original corner establishment:  
None.



Description of corner evidence found:

None, corner established by this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

At position determined by survey set a 2½" aluminum cap on a 2½" x 30" aluminum pipe, projecting 4" out of the ground with a mound of stone, (marked as shown in corner diagram).

Set a steel fence post alongside with signs 54-2 and 54-9 attached.

New Bearing Trees:

A 10" diameter white fir bears S 12° E, 28.0 feet marked "NW1/16S26BT" on double blaze.

A 9" diameter white fir bears N 69½° W, 14.5 feet marked "NW1/16S26BT" on double blaze.

Each new bearing tree has signs 54-3 and 54-9 attached below a 6" band of red paint. Each blaze is painted red and has a brass washer marked "PLS 1106" attached.

Compass declination 18° East.

Witnessed by: William L. Hanley, PLS  
Kelly Snively

REGISTERED PROFESSIONAL LAND SURVEYOR
---------------------------------------------

*Will R. Wells*

OREGON JULY 22, 1977 WILLIAM R. WELLS 1106
-----------------------------------------------------

Renews 6/30/98

Office of SURVEYOR County of GRANT  
 State of OREGON, I hereby certify that the within instrument was filed in this office  
 for record on the 18 day of DEC, 1996  
Robert H. Bayett by \_\_\_\_\_  
 (COUNTY OFFICIAL) (DEPUTY)