


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

At the corner position determined by survey set a 2 1/2"x30" galv. iron pipe
 with brass cap 29" in ground marked: T8S R35E
 From Which: C-N-S-N 1/256
 A Lodge Pole Pine 5" dia. bears N 23°E 2.4 ft. marked
 CNSN 1/256 S35 BT. +
 A Lodge Pole Pine 7" dia. bears S 38°E 29.4 ft. marked S35
 CNSN 1/256 S35 BT. PLS 1099
 1983


Attached brass washer stamped LS 1099 to BT blaze on both trees.

Corner location perpetuated in accord with Umatilla N.F. survey Contract no. 53-04R3-2-01275. 20°E Declination Steel Tape Post 5'+ East w/54-2 & 54-9 Post 5'+ West w/54-2

Corner falls at base of hill in edge of cut on south edge of meadow.

September 8, 1983 Witnesses: A. Ray Crapo
Kyle McKinney
Todd Olsen

Refer to Grant County Survey No. 828



Office of... SURVEYOR ... County of... GRANT ...
 State of... OREGON ... I hereby certify that the within instrument was filed in this office
 for record on the 30 day of... AUG ... 1984
Robert D. Leggett by
 (COUNTY OFFICIAL) (DEPUTY)