


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None


Description of monument and accessories established to perpetuate the original location of this corner:

At the corner position determined by survey set a 2 1/2"x30" galv. iron pipe with brass cap 29" in ground marked:

From which:

A 5/8"x30" iron rod with plastic AP-A cap bears N 30°E, 5.4 ft.- with guard post.

A 5/8"x30" iron rod with plastic APA cap bears N 83°E, 6.3 ft. with guard post.



No BT's available

Corner location perpetuated in accordance with Umatilla N.F. survey contract NO. 53-04R3-2-01275.

Post 5'+ North w/54-2 & 54-9

Post 5'+ East w/54-2

20°E Declination

Steel Tape

August 30, 1983

Witnesses: A. Ray Crapo
Greg Orton
Kyle McKinney

Corner falls in meadow.

Refer to Grant County Survey No. 828



Office of..... SURVEYOR County of..... GRANT

State of..... OREGON, I hereby certify that the within instrument was filed in this office for record on the 30 day of..... AUG., 1984

..... Robert O. Dwyer by (DEPUTY)

(COUNTY OFFICIAL)