


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

U-17

History of original corner establishment:

None



Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

At CORNER POSITION determined by survey set a 2 1/2"x30" galv. iron pipe with brass cap 28" in ground with raised mound of stone marked:

From which:

A Pond. Pine 16" dia. bears S43°E 40.5 ft. marked S1/16 S26 BT

A Pond. Pine 18" dia. bears S73°W 20.5 ft. marked S1/16 S27 BT

T8S R35E
S1/16

S27+S26

PLS 1099
1983

Attached brass washers stamped LS 1099 to BT blaze on both trees.

Corner location perpetuated in accord. with Umatialla N.F. Survey Contract No. 53-04R3-2-01275.

20° East Declination
Steel Tape


Post 5'± North with 54-2, 54-9

Corner in N-S draw 450'± from main road

Sept. 6, 1983

Witnesses: A. Ray Crapo
Kyle McKinney
Todd Olsen

Refer to Grant County Survey No. 828



Office of.....SURVEYOR..... County of.....GRANT.....
 State of.....OREGON..... I hereby certify that the within instrument was filed in this office
 for record on the.....30 day of.....NOV...... 19.....83
Robert H. Dwyer..... by.....
 (COUNTY OFFICIAL) (DEPUTY)

U-17