


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by Herman D. Gradon under GLO contract No. 499 dated March 11, 1884.

Surveyor's General records state:

Set a post 4 ft. long 4 ins. square 24 ins. in the ground for cor. to secs. 25, 26, 35, and 36 marked T 8 S S 25 on NE, R 35 E S 36 on SE, S 35 on SW, and S 26 on NW faces with 1 notch on S and E edges; from which



- A pine 10 ins diam bears N 38° E, 85 lks dist marked T 8 S R 35 E S 25 BT
- A pine 7 ins diam bears S 21° E, 79 lks dist marked T 8 S R 35 E S 36 BT
- A pine 10 ins diam bears S 29° W, 85 lks dist marked T 8 S R 35 E S 35 BT
- A pine 4 ins diam bears N 68° W, 100 lks dist marked T 8 S R 35 E S 26 BT

Description of corner evidence found:


A windblow snag 11 ins diam with full scribes on a partially opened blaze for section 26 BT.

At the record location as determined by the bearing tree found a mound of stone.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set a 2½ in. brass cap on a 2 in. iron pipe 31 ins. long 20 ins. in the ground with a surrounding rock mound.

Brass cap marked thus: T 8 S R 35 E



1979

ORLS 1639

New bearing tree:

A fir 6 ins. diam bears S 05° E, 78.8 ft dist mkd T 8 S R 35 E S 36 BT

No other live trees available within limits.

I hereby certify the above corner monument was properly re-established by me on Sept. 6, 1979 and witnessed by John Mitchell and Don Pedracini.

REGISTERED PROFESSIONAL LAND SURVEYOR
--

William L. Hanley

OREGON JULY 14, 1978 WILLIAM L. HANLEY 1639

Office of Surveyor County of Grant
 State of ORE I hereby certify that the within instrument was filed in this office
 for record on the 24 day of Sept, 1979
Robert D. Bayliff by _____
 (COUNTY OFFICIAL) (DEPUTY)

*CORNER updated
FILED Feb 1983*