


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Y.70-21

History of original corner establishment:

1998, Robert D. Bagett, Registered Land Surveyor 598, set a 5/8" X 30" iron pin with attached yellow plastic cap marked BGB SURVEY MARKER (Grant Co. Map of Survey No. 1489).



Description of corner evidence found:

Found a 5/8" rebar, with a 1 1/3" yellow plastic cap, projecting 2" out of the ground, marked as shown.



Description of monument and accessories I established to perpetuate the original location of this corner:

None

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David A Schlaich

OREGON
JULY 16, 1987
DAVID A. SCHLAICH
2308

RENEWAL DATE: 06/30/2000

Magnetic Declination 19° East
WORK PERFORMED BY: David A. Schlaich (RLS 2308)
WITNESSED BY: Michael McVeigh
DATE: October 14, 1999

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 9 day of FEB, to 2000
Robert D. Bagett by _____
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

SEE MAP OF SURVEY NO. 1543

Y.70-21