

CERTIFIED RECORD OF LAND CORNER MONUMENTATION


History of original corner establishment:

Corner established by Herman D. Gradon under GLO Contract No. 499 dated March 11, 1884.

Surveyor General's records state:

Set a post 3 ft long 3 ins square 24 ins in the ground for 1/4 sec cor marked 1/4 S on N face, from which:

- A pine 8 ins diam bears N. 45° W., 17 lks dist mkd 1/4 S BT
- A pine 6 ins diam bears S. 76° W., 23 lks dist mkd 1/4 S BT



Description of corner evidence found:

A mound of stone long accepted by local long-time residents as the 1/4 sec cor to sec 36 only.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set a 2½ inch brass cap on a 2 inch iron pipe 31 ins long 26 ins in the ground with a 6 ft steel fence post alongside with a sign 54-4 attached.

Brass cap marked thus: T 8 S R 35 E

$\frac{1}{4}$ S 36

T 9 S

1979
ORLS 1639

New bearing trees:

- A tamarack 8 ins diam bears N. 88° E., 037.4 ft dist mkd 1/4 S 36 BT
- A fir 6 ins diam bears N. 35° W., 108.5 ft dist mkd 1/4 S 36 BT

Each BT has a sign 54-3 attached below a band of red paint and has a brass washer marked LS 1639 nailed flush with BT blaze.

I hereby certify the above corner monument was properly re-established as herein described on June 13, 1979 witnessed by Tom Fisk and Tracy Labaree.

REGISTERED PROFESSIONAL LAND SURVEYOR
--

William L. Hanley

OREGON JULY 14, 1978 WILLIAM L. HANLEY 1639
--

Office of...County...Surveyor..... County of...Grant.....
 State of...Oregon... I hereby certify that the within instrument was filed in this office
 for record on the...20 day of...August....., 19...79
Robert D. Degett by
 (COUNTY OFFICIAL) (DEPUTY)