

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

V-1


History of original corner establishment:

Corner established by Otis O. Gould under special instructions dated Nov. 27, 1935, which provided for the surveys included under Group No. 179.

Surveyor General records state:

Set an iron post 3 ft long 1 in diam 27 ins in the ground for closing cor of secs 30 and 31 with brass cap as marked (in corner diagram) from which:

A tamarack 20 ins diam bears N19½°E, 43 lks dist marked T8SR36ES30CC BT.
A fir 10 ins diam bears S49½°E, 68 lks dist marked T8SR36ES31CC BT.



Description of corner evidence found:

Found a 2½" brass cap on a 2" iron pipe protruding 6" from mound of earth marked as shown in corner diagram.

A tamarack 23 ins diam bears N21°E, 28.2 ft with a healed blaze (record states: N19½°E, 43 lks).

A fir 18 ins dia bears S46½°E, 45.2 ft with healed blaze (record states S49½°E, 68 lks).

Description of monument and accessories established to perpetuate the original location of this corner:

Corner monument maintained to USFS standards as follows...cleared brush and debris from around cor monument. Placed 6' steel fence post N of cor with sign 54-9 attached.

Each original bearing tree has signs 54-3 and 54-9 attached below a 6 inch band of red paint.

Compass declination 19°East.

I hereby certify that the above corner monument was properly maintained to U.S.F.S. standards under my supervision and witnessed by Willard Hulick on August 2, 1986.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106

Office of.....County Surveyor..... County of...Grant.....
State of.....Oregon..... I hereby certify that the within instrument was filed in this office
for record on the...8... day of...Sept... , 1986
.....*Robert D. Bayett*..... by
(COUNTY OFFICIAL) (DEPUTY)