RECEIVED A
FILED
FEB 26 1973
JOHN LIVEIRA, County Clerk
By _____ Deputy

CORNER RESTORATION

SE cor.

CORNER Sec. 35 TWP 8 S., RANGE 27 E., W.M.
Standard Cor.

ORIGINAL SURVEY BY: Aaron S. York

CONTRACT NUMBER: 335

CONTRACT DATE: August 11,1879



ORIGINAL DESCRIPTION:

Set stone 16x12x8 for Standard Cor. to secs.35 and 36.
Raised stone mound at Cor.

RESTORATION BY, STAMP AND DATE:

REGISTERED
PROFESSIONAL
LAND SURVEYOR
Robert D. Bagett
OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

February 20,1973

EVIDENCE FOUND:

This corner was pointed out to me by Leo Flowers in 1970 and by Don Capon in 1973. The corner is a basalt stone 15x11x7 inches marked 8/27 SC with 5 notches on one edge. This corner stone was in a rock jack fence corner of fences running N.20°W., and N.87°E. This position is in harmony with the original calls to natural features to the East and West.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

At the corner point I set a 1½"x 36" iron pipe, 34 " in the ground with brass cap marked as shown. from which NEW BEARING TREES:
MONUMENT MARKED

A scrub juniper, 14 ins. diam., bears S.49°05'W., 57.1 ft., scribed X CS BT.

A juniper 10 ins. diam., bears N.85°45'E., 134.0 ft., scribed T8S R27E S36 CS BT.

I surrounded the pipe with a mound of stone and placed the original cor. stone South and alongside the pipe. Used steel tape and true bearings (solar). Measurements are to the face of the blaze on the BTs.

GRANT COUNTY SURVEYOR
SC
T 8S R 27E
S 35 | S 36
S 3
T9S R27E
1973
OPLS 598

Complete and File with Office of the Grant County Surveyor, Grant County, Oregon, Courthouse, Canyon City, Oregon 97820

Z-21