


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Original corner established by: Arron York, Deputy Surveyor, under Contract No. 335, dated August 11, 1879.

The Record States: Set stone 14x14x12, for corner to sections 19,20,29 and 30, stone mound at corner.



Description of corner evidence found:

The original corner stone was removed years ago while clearing the land for a new orchard. Everett Wheeler saw the marked stone at the position of a fence corner. John Thomas was present when the fence corner was removed and showed me the position of the original stone. I accept the testimony of these two local land owners to position the section corner.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

[Signature]
OREGON
SEPTEMBER 19, 1995
JACK L. WATSON
2734

RENEWAL DATE: 6/30/2002

Description of monument and accessories set at corner location:

At the position pointed out to me by Mr. Thomas, I set a 2½"x30" aluminum pipe with attached 3" aluminum cap, 30 inches in the ground, the cap is stamped as shown in the diagram.

From which I set new reference monuments:

A 5/8"x30" iron pin bears N51°E, 15.00 feet, with attached red plastic cap marked CORNERSTONE SURVEYING INC.

A 5/8"x30" iron pin bears S35°E, 20.00 feet, with attached red plastic cap marked CORNERSTONE SURVEYING INC.

A 5/8"x30" iron pin bears S51°W, 15.00 feet, with attached red plastic cap marked CORNERSTONE SURVEYING INC.

A 5/8"x30" iron pin bears N35°W, 20.00 feet, with attached red plastic cap marked CORNERSTONE SURVEYING INC.

I used magnetic compass, with 20° east variation and steel tape, to tie references.

Date: March 2, 2001

Office of SURVEYOR County of GRANT
State of OREGON, I hereby certify that the within instrument was filed in this office
for record on the 16 day of MARCH, 2001.
Robert D. Baggett by _____
(COUNTY OFFICIAL) (DEPUTY)