


CORNER RESTORATION



N $\frac{7}{2}$ Cor. _____ TWP 9S _____ RANGE 27E

ORIGINAL SURVEY BY: Aaron S. York

CONTRACT NUMBER: 335

CONTRACT DATE: August 11, 1879

ORIGINAL DESCRIPTION:

This $\frac{7}{2}$ cor. was not set by the government surveyors. W.F. White, previous Grant Co. Surveyor states in Book 1 page 53 of the Surveyors Record that he set this cor. in 1898, his record is as follows:
I then placed a stone marked thus $\frac{7}{2}$ CS 40.73 chs. west from the sec. cor. for secs. 4 and 5 on SS Tp line and raised stone mound around corner.

RESTORATION BY, STAMP AND DATE:

REGISTERED
OREGON
LAND SURVEYOR

Robert D. Baggett

JULY 12, 1963
ROBERT D. BAGGETT
598

BAGETT, GRIFFITH & FERGUSON
170 S. DAYTON - PH. 575-1251
JOHN DAY, OREGON 97845

Jan. 1971

EVIDENCE FOUND:

A diligent search for White's $\frac{7}{2}$ cor. produced no results. I placed the $\frac{7}{2}$ cor. on the Tp line and at mid-distance between the NE and NW corners of sec. 5. This position is harmoniously related to fences and improvements in sec. 5

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var. from which
Set a 1 $\frac{1}{2}$ "x36" iron pipe 32 ins. in the ground with brass cap mkd. as shown.
MONUMENT MARKED


A 10" juniper bears S.25°10'E, 169.7 ft, mkd

A 14" juniper bears S38°09'W 185.3 ft, mkd, T9S R27E
T9S R27E $\frac{7}{2}$ S5 BT.

Surround pipe with mound of stone.
Cor. is 6 ft. W. of old powerline & 12 ft. E of center of driveway to ranch house.

Set 2x4x60" wood post 1 $\frac{1}{2}$ ft N. of cor.

Complete and file with Office of the Grant County Surveyor, Grant County, Oregon, Courthouse, Canyon City, Oregon 97820



See Remon Deited May, 1971 Survey #213