


# CORNER RESTORATION

Center  $\frac{1}{4}$  cor.  
CORNER sec. 5 TWP 9S RANGE 27 E., WM

ORIGINAL SURVEY BY: Aaron S. York

CONTRACT NUMBER: 335

CONTRACT DATE: August 11, 1879



## ORIGINAL DESCRIPTION:

NONE

This cor has never been set before.

## RESTORATION BY, STAMP AND DATE:

BAGETT, GRIFFITH & FERGUSON  
170 S. DAYTON - PH. 575-1251  
JOHN DAY, OREGON 97845



*Robert D. Baggett*  
JULY 12, 1963  
ROBERT D. BAGETT  
598

January 23, 1971

## EVIDENCE FOUND:

NONE

Established at intersection of lines between opposite corresponding  $\frac{1}{4}$  corners.

## DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set  $5/8$ "x $30$ " iron pin 24 ins. in the ground for center  $\frac{1}{4}$  cor. of Sec. 5.

MONUMENT MARKED

from which


A juniper, 8 ins. diam., bears  $S.29^{\circ}W.$ , 42.0 ft., mkd.  $C\frac{1}{4}$  S5 BT.

A juniper, 10 ins. diam., bears  $N.62^{\circ}E.$ , 17.0 ft., mkd.  $C\frac{1}{4}$  S5 BT.

Raised mound of stone around pin. Pin is about 8 ft.

Complete and File with Office of the Grant W. of NS fence.

County Surveyor, Grant County, Oregon, Compass Var.  $20^{\circ}E.$  steel  
Courthouse, Canyon City, Oregon 97820 tape.



C-7

Survey # 213