


CORNER RESTORATION

E $\frac{1}{4}$ Cor.
 CORNER Sec. 5 TWP 9S RANGE 27E., WM

ORIGINAL SURVEY BY: Aaron S. York

CONTRACT NUMBER: 335

CONTRACT DATE: August 11, 1879



ORIGINAL DESCRIPTION:

North bet. secs. 4 & 5.

40.00 chs. set stone 14x11x11 for $\frac{1}{4}$ sec cor.
 Stone mound at cor.

January 23, 1971

RESTORATION BY, STAMP AND DATE:

BAGETT, GRIFFITH & FERGUSON
 170 S. DAYTON - PH. 575-1251
 JOHN DAY, OREGON 97845



Jan. 23, 1971

EVIDENCE FOUND: The original cor. was not found, it falls in field and has been destroyed by farming operations. I set the cor. at record dist. from the SE cor. of sec 5, (course at. is reduced to Lat.) and on line bet. the SE cor of sec 5 and the NE Closing Cor. of Sec 5. This position best fits improvements in the area and is harmoniously related to other found sec. cors. in secs. 4 and 5.

DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:

Show how trees are scribed and basis of bearings, including compass var.

Set a 1 $\frac{1}{2}$ "x36" iron pipe 36 ins. in the ground with brass cap mkd. as shown.


from which

MONUMENT MARKED.

A juniper, 12 ins. diam., brs. N.80°40'E., 258.7 ft., mkd. T9S R27E $\frac{1}{4}$ S4 BT.

A juniper 10 ins. diam., brs., N.47°38'W., 269.8 ft., mkd. T9S R27E $\frac{1}{4}$ S5 BT.

Surround pipe with stone to top of cap, and deposit beer bottle at base of pipe.



Complete and File with Office of the Grant
 County Surveyor, Grant County, Oregon,
 Courthouse, Canyon City, Oregon 97820

C-9

Survey # 713