


# CORNER RESTORATION



CORNER SW Cor. Sec. 12 TWP 9S RANGE 27E.W.M.

ORIGINAL SURVEY BY: Aaron S. York

CONTRACT NUMBER: 335

CONTRACT DATE: August 11, 1879

## ORIGINAL DESCRIPTION:

Set stone 14x12x8 for corner to Secs. 11, 12, 13 and 14. Raised mound of stone at corner.

## EVIDENCE FOUND:

Found a basalt stone 14x12x8 inches marked with 4 grooves on South face and 2 grooves on East face firmly set 10 inches in the ground and in a mound of stone.

## RESTORATION BY, STAMP AND DATE:

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

R. D. Bagett  
W. Gents

OREGON  
JULY 12, 1963  
ROBERT D. BAGETT  
598

March 18, 1977

Grant County Surveyor

## DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:


Show how trees are scribed and basis of bearings, including compass var.

At the corner point: Set a 1 1/2"x30" iron pipe 28 inches in the ground, with brass cap marked as shown.

I deposited an unbroken glass beer bottle at the base of the iron pipe.

I buried the original corner stone West and alongside the iron pipe and surrounded the pipe with a mound of stone.

No bearing trees or bearing objects available.



MONUMENT MARKED

RECEIVED AND FILED

APR 18 1977

JOHN LIVEIRA, County Clerk

By Deputy