

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:  
Corner has not been previously set.

DIAGRAM

T9S R31E

SE1/16 S15

1989  
PLS 699

Description of corner evidence found:  
Corner is being set by this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 2 1/2" aluminum cap, marked as shown in the diagram, 24" in the ground to hardpan, at a point as determined by the procedures set forth in the MANUAL OF INSTRUCTIONS FOR THE SURVEY OF PUBLIC LANDS for the subdivision of sections. Built a mound of rock to be 30" in diameter by 6" high around the monument, from which new BTs are:

10" Ponderosa pine bears S78°45'E, 26.9 feet scribed SE1/16 S15 BT

8" Ponderosa pine bears N25°15'E, 38.4 feet scribed SE1/16 S15 BT

Attached BT and Land Survey Monument signs to and painted a red band around each BT. Bearings were turned from the control traverse with a theodolite, basis of bearing being the bearing between corners G-13 and N-13 as shown on Grant County Map of Survey No. 634, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground. Set a steel fence post 5 feet S of the corner with a Land Survey Monument sign attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on November 20, 1989, I established the corner as herein described.

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR  
THIS 26 DAY OF July, 1990

Robert D. Baggett

Grant County Surveyor

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

Leland L. Myers  
OREGON  
JULY 9, 1965  
LELAND LEE MYERS  
699