

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by Rufus S. Moore, US Deputy Surveyor, during the original survey Contract No. 382 dated March, 1881.

Set a basalt stone XXXXXXXXXXXXXXXXXXXXXmade mounXXXXXX1/4 sec. cor. froXXXXXXXXXXXXXXXX

Juniper 26 ins. diam., bears XXXXXX(X's represent an ink spill on the original notes.)

DIAGRAM

T9S R31E

1/4

S21 | S22

1989

PLS 699

Description of corner evidence found:

Due to an ink spill on the original notes it was not possible to read any dimensions except the bearing tree diameter. Found an 18x9x6 stone with a rare mark of 1/4 on the down face.

24" Juniper (Dead & Down)(Scribing Visible)(1881 BT) bears unknown. It appears the BT was uprooted and moved from its ori position by road construction. Original position is not known.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 2 1/2" aluminum cap, marked as shown in the diagram, 24" in the ground to solid rock, replacing the rock which is turned upside down and buried on the north side of the monument. Improved the existing mound with rock to be 36" in diameter by 6" high around the monument, from which new BTs are:

8" Juniper bears S46°W, 16.3 feet scribed 1/4 S21 BT

6" Juniper bears N10°45'W, 30.2 feet scribed 1/4 S22 BT

A Silver DEEP buried 6" in the ground bears N46°E, 2.0' with a brass washer inside stamped PLS 699

A Pink DEEP buried 4" in the ground bears S10°45'E, 2.0' with a brass washer inside stamped PLS 699

Attached BT and Attention signs to and painted a red band around each BT. Bearings were turned from the control traverse with a theodolite, basis of bearing being the bearing between corners G-13 and N-13 as shown on Grant County Map of Survey No. 634, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground.

Set a steel fence post 5 feet S of the corner with an Attention sign attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on September 7, 1989, I monumented the corner as herein described.

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 26 DAY OF July, 1990

Robert D. Bayless
Grant County Surveyor

REGISTERED PROFESSIONAL LAND SURVEYOR

Leland L. Myers

OREGON JULY 9, 1965 LELAND LEE MYERS 699