

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by Rufus S. Moore, US Deputy Surveyor, during the original survey Contract No. 382 dated March, 1881.

Set a fir post for cor. to secs. 20, 21, 28, 29 from which a

- Pine 34 ins. diam., bears N53°E, (23.10') 35 lks. dist.
- Fir 9 ins. diam., bears N53°W, (24.42') 37 lks. dist.
- Fir 9 ins. diam., bears S39°W, (17.82') 27 lks. dist.
- Pine 18 ins. diam., bears S13°E, (34.32') 52 lks. dist.

DIAGRAM

T9S R31E

S20	S21
S29	S28

1989
PLS 699

Description of corner evidence found:

The original field notes call for an "old wagon road" 4.50 chains to the East and 2.65 chains North of the corner. This old road is still evident and was used to help isolate the corner search area. It is probable that remains of the SE bearing tree and the root hole for the NE BT were found.

Found old E-W blazes on a tree very near the corner location. The control survey also supported the probable corner location. The corner was set based on all this supportive evidence.

Possible root hole at record, 9" Fir (1881 BT) not found, 9" Fir (1881 BT) not found, Possible root and stump core at record

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 2 1/4" aluminum cap, marked as shown in the diagram, 26" in the ground, based on supportive evidence and topographic calls to an old wagon road. Built a mound of rock to be 30" in diameter by 4" high around the monument, from which new BTs are:

- 11" Douglas-fir bears N29°W, 9.6 feet scribed T9SR31E S20 BT
- 12" Douglas-fir bears S80°E, 16.0 feet scribed T9SR31E S21 BT
- 7" Douglas-fir bears S10°15'E, 15.5 feet scribed T9SR31E S28 BT
- 14" Douglas-fir bears S27°W, 22.9 feet scribed T9SR31E S29 BT

Attached BT and Attention signs to and painted a red band around each BT. Bearings were turned from the control traverse with a theodolite, basis of bearing being the bearing between corners G-13 and N-13 as shown on Grant County Map of Survey No. 634, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground.

Set a steel fence post 5 feet W of the corner with an Attention sign attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on October 16, 1989, I re-established the corner as herein described.

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 26 DAY OF July, 19 90

Robert D. Baggett
Grant County Surveyor

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
JULY 9, 1965
LELAND LEE MYERS
699