

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by Rufus S. Moore, US Deputy Surveyor, during the original survey Contract No. 382 dated March, 1881.

Set a pine post for 1/4 sec. cor. from which a
Pine 20 ins. diam., bears N15°W, (6.60') 10 lks. dist.
Fir 9 ins. diam., bears S42°W, (8.58') 13 lks. dist.

DIAGRAM

T9S R31E

S21
1/4—
S28

1989
PLS 699

Description of corner evidence found:

No evidence of the original corner was found. The location is in or near an old logging skid road.

20" Pine (1881 BT) not found. 9" Fir (1881 BT) not found.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 2 1/2" aluminum cap, marked as shown in the diagram, 24" in the ground, at single proportionate measurements from adjacent found corners. Built a mound of rock to be 30" in diameter by 4" high around the monument, from which new BTs are:

12" Douglas-fir bears S13°30'W, 37.5 feet scribed 1/4 S28 BT

19" White fir bears N74°E, 21.3 feet scribed 1/4 S21 BT

A Blue DEEP buried 12" in the ground bears S74°W, 2.0' with a brass washer inside stamped PLS 699

A Silver DEEP buried 16" in the ground bears N13°30'E, 2.0' with a brass washer inside stamped PLS 699

Attached BT and Attention signs to and painted a red band around each BT. Bearings were turned from the control traverse with a theodolite, basis of bearing being the bearing between corners G-13 and N-13 as shown on Grant County Map of Survey No. 634, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground.

Set steel fence posts 5 feet N and 5 feet W of the corner on the National Forest boundary lines. Attached Forest Boundary signs to each post and an Attention sign to the N post.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on October 30, 1989, I re-established the corner as herein described.

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 26 DAY OF July, 1990

Robert D. Bayitt
Grant County Surveyor

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Leland L. Myers
OREGON
JULY 9, 1965
LELAND LEE MYERS
699