

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by Rufus S. Moore, US Deputy Surveyor, during the original survey Contract No. 382 dated March, 1881.

DIAGRAM

T9S R31E

1/4

S29 | S28

1989

PLS 699

Set a fir post for 1/4 sec. cor. from which a Tamarack 24 ins. diam., bears N75°W, (3.30') 5 lks. dist. Fir 6 ins. diam., bears S62°E, (7.92') 12 lks. dist.

Description of corner evidence found:

None of the original post was found.

24" Tamarack (1881 BT) not found. 6" Fir (1881 BT) not found.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 2 1/4" aluminum cap, marked as shown in the diagram, 24" in the ground, at single proportionate measurements from adjacent found corners on the edge of the creek bed. Built a mound of rock to be 30" in diameter by 6" high around the monument, from which new BTs are:

6" Ponderosa pine bears S81°45'W, 74.3 feet scribed 1/4 S29 BT

19" Western larch bears N26°E, 63.0 feet scribed 1/4 S28 BT

A Blue DEEP buried 12" in the ground bears S26°W, 2.0' with a brass washer inside stamped PLS 699

A Silver DEEP buried 12" in the ground bears N91°45'E, 2.0' with a brass washer inside stamped PLS 699


Attached BT and Attention signs to and painted a red band around each BT. Bearings were turned from the control traverse with a theodolite, basis of bearing being the bearing between corners G-13 and N-13 as shown on Grant County Map of Survey No. 634, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground.

Set steel fence posts 5 feet S and 5 feet E of the corner on the National Forest boundary lines. Attached Forest Boundary signs to each post and an Attention sign to the S post.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on October 17, 1989, I re-established the corner as herein described.



Leland L. Myers



FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 26 DAY OF July, 1990

Robert D. Sagett
Grant County Surveyor