

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by Rufus S. Moore, US Deputy Surveyor, during the original survey Contract No. 382 dated March, 1891.

Set a pine post for cor. to secs. 27, 28, 33, 34 from which a

- Pine 10" ins. diam., bears N14°E, (44.88') 68 lks. dist.
- Pine 36 ins. diam., bears N67°W, (44.22') 67 lks. dist.
- Pine 42 ins. diam., bears S75°W, (6.60') 10 lks. dist.
- Pine 10 ins. diam., bears S73°E, (53.46') 81 lks. dist.

DIAGRAM

T9S R31E

S28	S27
S33	S34

1989
PLS 699

Description of corner evidence found:

The corner position has a logging skid road through it so no evidence of the original post was found.

- 27" Ponderosa pine (Good Condition)(Blaze Opened by Others)(1891 BT) bears N14°E, 46.0 feet.
- 34" Ponderosa pine (Good Condition)(Scribing Visible)(1891 BT) bears N66°30'W, 42.6 feet.
- 31" Ponderosa pine (Good Condition)(Blaze Healed Over)(1891 BT) bears S72°30'E, 51.6 feet.
- 42" Pine (1891 BT) not found.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 2 1/2" aluminum cap, marked as shown in the diagram, 26" in the ground 26", at the point determined by the bearing trees. Built a mound of rock to be 24" in diameter by 4" high around the monument, from which new BTs are:

- 9" Ponderosa pine bears S2°15'W, 43.1 feet scribed T9SR31E S33 BT
- 10" Ponderosa pine bears N9°15'W, 25.3 feet scribed T9SR31E S28 BT

Attached BT and Attention signs to and painted a red band around each BT. Bearings were turned from the control traverse with a theodolite, basis of bearing being the bearing between corners G-13 and N-13 as shown on Grant County Map of Survey No. 634, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground.

Set a steel fence post 5 feet N of the corner with an Attention sign attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on October 18, 1989, I monumented the corner as herein described.

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR
THIS 26 DAY OF July, 1990

Robert D. Bayett
Grant County Surveyor

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Leland L. Myers

OREGON
JULY 9, 1965
LELAND LEE MYERS
699