

**CERTIFIED RECORD OF LAND CORNER MONUMENTATION**

**History of original corner establishment:**  
Corner has not been previously set.

**DIAGRAM**  
  
T9S R32E  
  
C1/4 S11  
  
1986  
PLS 699

**Description of corner evidence found:**  
Corner is being set by this survey.

**Description of monument and accessories I established to perpetuate the original location of this corner:**


Set a 2"x30" aluminum pipe with a 3 1/4" aluminum cap, marked as shown in the diagram, 28" in the ground, at a point as determined by the procedures set forth in the MANUAL OF INSTRUCTIONS FOR THE SURVEY OF PUBLIC LANDS for the subdivision of sections. Due to the steepness and looseness of the ground a mound is impractical, from which new BTs are:

- 7" Mountain mahogany bears N8° 30'E, 15.5 feet scribed C1/4 S11 BT
- 6" Mountain mahogany bears N58° 15'E, 21.3 feet scribed C1/4 S11 BT

Attached BT and Land Survey Monument signs to and painted a red band around each BT. Bearings were turned from the control traverse with a theodolite, basis of bearing being a solar observation, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground. Set a steel fence post 5 feet S of the corner with a Land Survey Monument sign attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on September 24, 1986, I established the corner as herein described.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR



OREGON  
JULY 9, 1965  
LELAND LEE MYERS  
699

**FILED**

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 23 DAY OF Feb, 1987

Robert D. Bayless  
Grant County Surveyor