

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by Herman D. Gradon, US Deputy Surveyor, during the original survey Joint Contract No. 416 dated August, 1881.

A point about 150 ft. above ravine;
Set basalt stone 14x10x10 ins. 9 ins. in the ground for Cor. to Secs 22, 23, 26 & 27 marked with 2 notches on S & E edges and raised a mound of stone alongside.

DIAGRAM

T9S R32E

S22 | S23
S27 | S26

1986
PLS 699

Description of corner evidence found:

The corner location is on a scab-rock hillside near a three-way fence corner. The fence corner is a large rock crib and the fence is supported by rock jacks at nearly every post. No evidence of the corner could be found. The corner stone and mound may be in the crib or used in one of the rock jacks.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 3 1/4" aluminum cap, marked as shown in the diagram, 24" in the ground to rock, at double proportionate measurements from adjacent found corners. Built a mound of rock & earth to be 42" in diameter by 6" high around the monument.

No new bearing trees set because no trees are within the allowable limits.

No. 5 rebar Reference Monument bears N2° 45'E, 9.8 feet marked RN ↓ 9.8' 1986 PLS 699

No. 5 rebar Reference Monument bears N86° 45'E, 9.6 feet marked RN ← 9.6' 1986 PLS 699

Set steel fence posts 5 feet N and 5 feet S of the corner on the National Forest property lines. Attached Forest Boundary signs to each post and an Attention sign to the N post.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on August 18, 1986, I re-established the corner as herein described.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Leland L. Myers

OREGON
JULY 9, 1969
LELAND LEE MYERS
699

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 23 DAY OF FEB, 1987

Robert D. Sapp
Grant County Surveyor