


# CORNER RESTORATION

**CORNER:** SW1/16 SEC. 27, TWP. 9 S., RANGE 32 E., W.M.

**ORIGINAL SURVEY BY:** Corner

**CONTRACT NUMBER:** Not Previously

**CONTRACT DATE:** Established



---

**ORIGINAL GLO DESCRIPTION:** None, corner not previously established.


---

**EVIDENCE FOUND:** None, corner not previously established.  
SEE RECORD MAP OF SURVEY NO. 1978

---

**DESCRIPTION OF MONUMENTS AND ACCESSORIES SET AND METHODS USED:** At the corner point, I set a 5/8"x15" iron pin with attached 1 1/2" aluminum cap, driven 13" in the ground to bedrock. I built a 2 foot mound of stone around the cap.

**FROM WHICH, I SET THE FOLLOWING REFERENCE POINTS:**  
A 5/8"x30" iron pin bears N.80°11'E., 27.09 feet with attached yellow plastic cap marked BENCHMARK SURVEYING;  
A 5/8"x30" iron pin bears N.26°25'W., 28.01 feet with attached yellow plastic cap marked BENCHMARK SURVEYING;  
Used RTK GPS to measure the reference points. Bearings are based on Map of Survey No. 1978



---

**RESTORATION BY, STAMP AND DATE:**

Michael C. Springer, PLS,  
and  
Jason L. Hatfield, PLS


P.O. Box 476  
217 N. Canyon Blvd.  
John Day, OR 97845

Surveyed May 24, 2013

RECEIVED AND FILED  
GRANT COUNTY SURVEYOR

MAY 30 2013

BY:



EXPIRES: 6/30/2014