

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by William R. Gradon,
US Deputy Surveyor, during the original survey
Contract No. 519 dated October, 1884.

Set a post $3\frac{1}{2}$ ft long 3 ins square 24 ins. in the
ground, for $\frac{1}{4}$ sec. cor. marked $\frac{1}{4}$ S on N face,
from which

A black pine 7 ins diam bears N25°E, (27.7')42 lks dist marked $\frac{1}{4}$ S BT

A black pine 8 ins diam bears S35°E, (30.4')46 lks dist marked $\frac{1}{4}$ S BT

DIAGRAM

T9S R33E

S19
 $\frac{1}{4}$ —
S30

1986
PLS 699

Description of corner evidence found:

Found a firmly set granite rock in a mound of rock rather than the original post. The rock may have been set when evidence of the original corner was still in existence. Other corners in the area at which stones in place of posts were found and original corner evidence was found the stones were properly set. The computed corner location was very close to the rock's position. The rock was accepted as the corner.

The 7" & 8" black pine (1884 BTs) not found.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a $3\frac{1}{4}$ " aluminum cap, marked as shown in the diagram, 26" in the ground, replacing the rock. Improved the existing mound with rock & earth to be 24" in diameter by 4" high around the monument, from which new BTs are:

7" Lodgepole pine bears N56° 15'E, 6.4 feet scribed $\frac{1}{4}$ S19 BT

7" Lodgepole pine bears S50° 30'E, 28.2 feet scribed $\frac{1}{4}$ S30 BT

Attached BT and Attention signs to and painted a red band around each BT. Bearings were taken with a staff compass, using a declination of 18° 30'E, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground.

Set a steel fence post 5 feet W of the corner with an Attention sign attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877,
do hereby certify that on August 5, 1986, I monumented
the corner as herein described.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 9, 1965
LELAND LEE MYERS
699

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 27 DAY OF Feb, 1987

Robert D. Smith
Grant County Surveyor