

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by William R. Gradon, US Deputy Surveyor, during the original survey Contract No. 519 dated October, 1884.

Set a post 4 ft long 4 ins square 24 ins in the ground for Cor. to Sec's 19, 20, 29 & 30, marked T9S S20 on NE, R33E S29 on SE, S30 on SW and S19 on NW faces with 2 notches on S and 5 notches on E edge from which

- A black pine 12" ins in diam bears N25°E, (86.5')131 lks dist. marked T9SR33E S20 BT
- A black pine 6 ins in diam bears S17°E, (8.6')13 lks dist. marked T9SR33E S29 BT
- A black pine 7 ins in diam bears S20°W, (19.8')30 lks dist. marked T9SR33E S30 BT
- A black pine 12 ins in diam bears N37°W, (59.4')90 lks dist. marked T9SR33E S19 BT

DIAGRAM

T9S R33E

S19	S20
S30	S29

1986
PLS 699

Description of corner evidence found:

Rock mound instead of post at correct distance from original BT remains.

- 12" Lodgepole pine (12" Stump)(Scribing Visible)(1884 BT) bears S14° 45'E, 8.7 feet.
- 14" Lodgepole pine (2" Broken Stub)(Scribing Visible)(1884 BT) bears S20° 45'W, 19.3 feet.
- The two 12" black pine (1884 BTs) not found.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 3/4" aluminum cap, marked as shown in the diagram, 26" in the ground, in rock mound and from the bearing trees. Improved the existing mound with rock to be 34" in diameter by 4" high around the monument, from which new BTs are:

- 9" Western larch bears N13° 15'W, 79.6 feet scribed T9SR33E S19 BT
- 6" Western larch bears N11°E, 82.9 feet scribed T9SR33E S20 BT
- 9" Western larch bears S45° 15'E, 135.8 feet scribed T9SR33E S29 BT

No tree available in Section 30.

Attached BT and Attention signs to and painted a red band around each BT. Bearings were turned from the control traverse with a theodolite, basis of bearing being a solar observation, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground.

Set a steel fence post 5 feet W of the corner with an Attention sign attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on August 2, 1986, I established the corner as herein described.

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 23 DAY OF Feb, 1987

Robert D. Baggett
Grant County Surveyor

