

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner has not been previously set.

DIAGRAM

T9S R33E

W1/16 $\frac{S20}{S29}$

1986
PLS 699

Description of corner evidence found:

Corner is being set by this survey.

Description of monument and accessories established to perpetuate the original location of this corner:



Set a 2"x30" aluminum pipe with a 3 1/4" aluminum cap, marked as shown in the diagram, 26" in the ground, at a point as determined by the procedures set forth in the MANUAL OF INSTRUCTIONS FOR THE SURVEY OF PUBLIC LANDS for the subdivision of sections. Built a mound of earth & rock to be 26" in diameter by 4" high around the monument, from which new BTs are:

6" Western larch bears N37° 45'E, 4.4 feet scribed W1/16 S20 BT

12" Western larch bears S37° 15'E, 34.5 feet scribed W1/16 S29 BT

Attached BT and Land Survey Monument signs to and painted a red band around each BT. Bearings were turned from the control traverse with a theodolite, basis of bearing being a solar observation, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground. Set steel fence posts 5 feet S and 5 feet W of the corner on the National Forest property lines. Attached Forest Boundary signs to each post and a Land Survey Monument sign to the S post.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on September 8, 1986, I established the corner as herein described.



FILED

IN THE OFFICE OF THE GRANT COUNTY SURVEYOR

THIS 23 DAY OF Feb, 1987

Robert D. Seibert
Grant County Surveyor