

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by William R. Gradon, US Deputy Surveyor, during the original survey Contract No. 519 dated October, 1884.

Set a post 4 ft long 4 ins square 24 ins in the ground for Cor. to Sec's 20, 21, 28 & 29, from which

- A tamarack 8 ins in diam bears N78°E, (6.6') 10 lks dist. marked T9SR33E S21 BT
- A black pine 12 ins in diam bears S32°E, (12.5') 19 lks dist. marked T9SR33E S28 BT
- A black pine 9 ins in diam bears S64°W, (13.9') 21 lks dist. marked T9SR33E S29 BT
- A tamarack 10 ins in diam bears N31°W, (21.1') 32 lks dist. marked T9SR33E S20 BT

DIAGRAM

T9S R33E

S20	S21
S29	S28

1986
PLS 699

Description of corner evidence found:

No evidence of the original post was found.

- 17" Western larch (Good Condition) (Blaze Opened by Others) (1884 BT) bears N72°E, 7.4 feet.
- 12" Lodgepole pine (2' Broken Stub) (Scribing Visible) (1884 BT) bears S30° 45'E, 12.7 feet.
- 11" Western larch (Good Condition) (Scribing Visible) (1884 BT) bears N28°W, 21.5 feet.
- 9" black pine (1884 BT) not found.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 3 1/4" aluminum cap, marked as shown in the diagram, 26" in the ground, at the point determined by the bearing trees. Built a mound of rock & earth to be 30" in diameter by 4" high around the monument, from which new BTs are:

- 9" White fir bears S46° 45'E, 20.4 feet scribed T9SR33E S28 BT
- 9" White fir bears S42° 15'W, 12.3 feet scribed T9SR33E S29 BT

Attached BT and Attention signs to and painted a red band around each BT. Bearings were taken with a staff compass, using a declination of 18° 30'E, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground.

Set a steel fence post 5 feet N of the corner with an Attention sign attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on August 11, 1986, I monumented the corner as herein described.

FILED

IN THE OFFICE OF THE GRANT COUNTY SURVEYOR

THIS 23 DAY OF Feb, 1987

Robert D. Buzell
Grant County Surveyor

