

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by William R. Gradon, US Deputy Surveyor, during the original survey Contract No. 519 dated October, 1884.

Set a post 4 ft long 4 ins square 24 ins in the ground for Cor. to Sec's 29, 30, 31 & 32, marked T9S S29 on NE, R33E S32 on SE, S31 on SW and S30 on NW faces with 1 notch on S and 5 notches on N edge from which

- A black pine 10 ins in diam bears N38°E, (23.1')35 lks dist. marked T9SR33E S29 BT
- A black pine 8 ins in diam bears S57°E, (35.0')53 lks dist. marked T9SR33E S32 BT
- A black pine 10 ins in diam bears S25°W, (62.0')94 lks dist. marked T9SR33E S31 BT
- A black pine 10 ins in diam bears N15°W, (6.6')10 lks dist. marked T9SR33E S30 BT

DIAGRAM

T9S R33E

S30	S29
S31	S32

1986
PLS 699

Description of corner evidence found:

A rock and rock mound instead of a post at the correct distance from the one remaining bearing tree.

- 8" Lodgepole pine (Dead & Down) (Scribing Visible) (1884 BT) bears S24°W, 62.4 feet.
- 10" black pine 8" black pine and 10" black pine (1884 BTs) not found.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 3/4" aluminum cap, marked as shown in the diagram, 24" in the ground, replacing the unmarked rock which was not of record. Improved the existing mound with rock & earth to be 30" in diameter by 6" high around the monument, from which new BTs are:

- 6" Western larch bears N86° 15'W, 20.8 feet scribed T9SR33E S30 BT
- 5" Lodgepole pine bears N39° 15'E, 27.8 feet scribed T9SR33E S29 BT
- 5" Lodgepole pine bears S23° 30'E, 25.4 feet scribed T9SR33E S32 BT
- 18" Western larch bears S47° 30'W, 54.5 feet scribed T9SR33E S31 BT

Attached BT and Attention signs to and painted a red band around each BT. Bearings were turned from the control traverse with a theodolite, basis of bearing being a solar observation, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground.

Set a steel fence post 5 feet N of the corner with an Attention sign attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on August 2, 1986, I monumented the corner as herein described.

FILED

IN THE OFFICE OF THE GRANT COUNTY SURVEYOR
THIS 23 DAY OF Feb, 1987

Leland L. Myers
Grant County Surveyor

