

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by Herman D. Gradon, US Deputy Surveyor, during the original survey Joint Contract No. 383 dated March, 1881.

Set stone 14x12x5 for cor to Townships 9. & 10 South, Ranges 32 & 33 East from which

- A fir 10 ins diam bears N80°W, (50.8') 77 lks dist
- A pine 10 ins diam bears N37°E, (19.8') 30 lks dist
- A pine 12 ins diam bears S33°E, (40.9') 62 lks dist
- A pine 20 ins diam bears S37°W, (9.9') 15 lks dist

DIAGRAM

T9S
R32E R33E
S36 | S31
S 1 | S 6
T10S
1986
PLS 699

Description of corner evidence found:

The original stone was not found. There is a rock mound with a 3/4" pipe alongside at the proper distance from the BTs. The corner is on a very steep slope with logging activity and the original stone probably has gone down the hill.

18" Douglas-fir (Dead & Down) (Scribing Visible) (1881 BT) bears at record Record distance appears to have been slope distance. The BT is about 20' downhill from the original position.

22" Ponderosa pine (Good Condition) (Blaze Opened by Others) (1881 BT) bears N47°E, 20.8 feet.

18" Ponderosa pine (Fair Condition) (Blaze Opened by Others) (1881 BT) bears S26°E, 41.5 feet.

Stump Hole (1881 BT) bears at record

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 3/4" aluminum cap, marked as shown in the diagram, 20" in the ground to rock, at the point determined by the bearing trees and at the rock mound. Improved the existing mound with rock & earth to be 40" in diameter by 10" high around the monument, from which new BTs are:

14" Douglas-fir bears N42° 30'W, 20.4 feet scribed T9SR32E S36 BT

11" Douglas-fir bears S5°W, 90.7 feet scribed T10SR32E S1 BT

Attached BT and Attention signs to and painted a red band around each BT. Bearings were taken with a staff compass, using a declination of 18° 30'E, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground.

Set a steel fence post 5 feet S of the corner with an Attention sign attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on August 31, 1986, I monumented the corner as herein described.

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 23 DAY OF Feb, 1987

Robert D. Geph
Grant County Surveyor

