

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner was established by Herman D. Graddon, US Deputy Surveyor, during the original survey Joint Contract No. 383 dated March, 1881.

Set post for 1/4 sec. cor. from which

A fir 12 ins diam bears S10°E, (5.9') 19 lks dist

A pine 18 ins diam bears N35°W, (15.2') 23 lks dist

DIAGRAM

T9S R33E

S31
1/4 ---
S 6

T10S
1986
PLS 699

Description of corner evidence found:

No evidence of the original post was found.

28" Douglas-fir (Good Condition) (Blaze Opened by Others) (1881 BT) bears S15°E, 6.3 feet.

Stump Hole (1881 BT) bears at record.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2"x30" aluminum pipe with a 3 1/4" aluminum cap, marked as shown in the diagram, 26" in the ground, at the point determined by the bearing trees. No rocks available to build a mound, from which a new BT is:

13" Ponderosa pine bears N27° 15'W, 10.0 feet scribed 1/4 S31 BT

Attached BT and Attention signs to and painted a red band around each BT. Bearings were taken with a staff compass, using a declination of 18° 30'E, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground.

Set a steel fence post 5 feet E of the corner with an Attention sign attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on August 31, 1986, I monumented the corner as herein described.

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 23 DAY OF Feb, 1987

Robert D. Gupta
Grant County Surveyor

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Leland L. Myers
OREGON
JULY 9, 1965
LELAND LEE MYERS
699