# CERTIFIED RECORD OF LAND CORNER MONUMENTATION

**History of original corner establishment:**

Corner was established by Rufus S. Moore, US Deputy Surveyor, during the original survey Contract No. 382 dated March, 1881.

Set a pine post for 1/4 sec. cor. from which a

Pine 24 ins. diam., bears N26°E, (58.00') 88 lks. dist.

Pine 8 ins. diam., bears S29°W, (40.92') 62 lks. dist.

DIAGRAM

T9S R31E

1/4

S15 | S14

1989
PLS 699

**Description of corner evidence found:**

Did not find any evidence of the original post. There was a mound of stone approximately 10' NE of the corner location that appears to have been set for the corner. The bearing trees conclusively proofed the corner location.

An uprooted stump and stump hole (No visible scribing)(1881 BT) bears at record.

23" Ponderosa pine (12" Stump)(Chaining notch cut out 10" deep)(1881 BT) bears S29°45'W, 40.7 feet.

**Description of monument and accessories I established to perpetuate the original location of this corner:**

Set a 2"x30" aluminum pipe with a 2½" aluminum cap, marked as shown in the diagram, 24" in the ground to hardpan, at the point determined by the bearing trees. Built a mound of rock to be 30" in diameter by 6" high around the monument, from which new BTs are:

8" Ponderosa pine bears S74°45'W, 18.2 feet scribed 1/4 S15 BT

10" Ponderosa pine bears S14°E, 32.6 feet scribed 1/4 S14 BT

An Orange DEEP buried 6" in the ground bears N14°W, 2.0' with a brass washer inside stamped PLS 699

A Silver DEEP buried 8" in the ground bears N74°45'E, 2.0' with a brass washer inside stamped PLS 699

Attached BT and Attention signs to and painted a red band around each BT. Bearings were turned from the control traverse with a theodolite, basis of bearing being the bearing between corners G-13 and N-13 as shown on Grant County Map of Survey No. 634, to stamped brass washers nailed in the scribed red-painted blazes. Distances were measured from a 60d spike, with an aluminum washer stamped PLS 699, which was driven into the side of each BT approximately one foot above the ground.

Set a steel fence post 5 feet N of the corner with an Attention sign attached. The monument is not a National Forest property corner.

I, Leland L. Myers, P.O. Box 98, Sumpter, OR 97877, do hereby certify that on November 19, 1989, I monumented the corner as herein described.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 9, 1965
LELAND LEE MYERS
699

FILED

IN THE OFFICE OF THE Grant COUNTY SURVEYOR

THIS 26 DAY OF July, 1990

Grant County Surveyor

USDA-FS Contract No. 53-04KK-8-02421 1151 T9S R31E L-17